

November 14, 2019

2726 W Cortez HOA 2726 W Cortez Chicago, IL

RE: Inspection of on going masonry work at above address on 11-4-19

A picture of a CMU Concrete Masonry Unit which is part of the east wall is enclosed. The pictures shows multiple pin holes in the PITFLEX coating. This is not up to the standards set by the manufacturer PPG.

This picture is consistent with other exterior wall areas.

PPG should have a rep to verify installation of there product using company standards. It is my understanding that 2 coats should be installed and final product verified by PPG for a warranty.

Did the installer follow PPG guidelines?

Steve Hier

Miller-Hier Entreprises

Please refer to 9-14-18 report



3080 W. Palmer Square = Chicago, IL 60647 = 773/342-4722 = 773/342-6090 Fax

Established in 1986

